## INSPECTION REPORT REVIEW POTENTIAL HAZARDOUS WASTE SITE

| SITE NAME: Dixie (TIE) Petro-chemical  LOCATION: Longview, TX  SITE NUMBER: TXD079836763 - Site Survey Date: 5 /24/93 INSPECTED BY: STATE FIT TAT OTHER:  LABORATORY: CLPEPAOTHER   |
|---|
| RECEIVED FROM: Borry Winnamoon DATE RECEIVED: 1 128/94  |
| SAMPLE TYPE(s):   |
| SOIL SURFACE WATER GROUND WATER OFF / on -site  |
| FOLLOW UP (Y/N):  |
| Locate Drinking Water Sources  (Re)Sampling Requested  Keep Site Active ("N"=No Further Action)  Concur with Report Recommendations   |
| SUMMARY: This is a review of an SSI report. The site was the location of a commercial repackaging facility of bulk industrial solvents (including hazardous materials) from 1979 to 1986.   |
| The pertinent aquifers dip in NE direction. Two private wells located in ae and SE direction at about 1 to 1.5 miles from site, were sampled. There were no significant detections of organic compounds in these samples. Only lead was detected at 3 times background and barium and zinc at above background concentrations. Due to the distance to the wells, these contaminants are not necessarily attributable to the site, and Superfund considers there is "no observed release to ground water". The are no downstream surface water intakes within the 15 mile target distance. |
| Only 5 drinking water wells are within the 4 mile target radius. There are about 800, 21,000 and 45,000 people within a 1, 2 and 4 mile radius, respectively.   |
| Based on a prescore analysis, the site will not warrant consideration as a NPL candidate.   |
| RECOMMENDATION: Concur with Superfund recommendation for a site evaluation accomplished determination.  |
| NOTE: On page 11, paragraph 3, statement indicates that DW18 is background sample and DW20 contains contaminants above BG. Table 4 indicates that DW20 is background sample. It appears either way will not affect decision.  |
| Concurrence: ENGINEER/REVIEWER  |
| ENGINEER/REVIEWER  90068896   |